



## Adrenaline Configurator Results -- Basic

Scanners listed with a software engine are considered "certified devices" with that engine. For certified devices, Kofax maintains two or more units in-house, tests them for all major product releases, and provides support for field-reported bugs.

Although **all configurations below are supported**, a (\*) indicates a Recommended Configuration. **Red text** indicates a configuration that is coming soon.

Scanner	Hardware Accelerator	Software Engine	Cable	
<a href="#">Agfa ADMIS S 31 SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1026-0000	*
<a href="#">Agfa ADMIS S 31 SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1026-0000	*
<a href="#">Agfa ADMIS S 31 SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<hr/>				
<a href="#">Bell &amp; Howell 1000FB/5000F SCSI</a>	Adrenaline 850 SCSI	n/a	SC-1026-0000	*
<a href="#">Bell &amp; Howell 1000FB/5000F SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1026-0000	*
<a href="#">Bell &amp; Howell 1000FB/5000F SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1026-0000	*
<a href="#">Bell &amp; Howell 1000FB/5000F SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	
<a href="#">Bell &amp; Howell 1000FB/5000F SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<hr/>				
<a href="#">Bell &amp; Howell 1000FB/5000F Video</a>	Adrenaline 850 Video	n/a	SC-1010-0000	*
<a href="#">Bell &amp; Howell 1000FB/5000F Video</a>	Adrenaline 1700 Video	n/a	SC-1010-0000	
<hr/>				
<a href="#">Bell &amp; Howell 2000D FB SCSI</a>	Adrenaline 850 SCSI	n/a	SC-1026-0000	*
<a href="#">Bell &amp; Howell 2000D FB SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	
<a href="#">Bell &amp; Howell 2000D FB SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<hr/>				
<a href="#">Bell &amp; Howell 2020D VRS Video</a>	Adrenaline 850 Video	n/a	Inc. w/Scanner	*
<a href="#">Bell &amp; Howell 2020D VRS Video</a>	Adrenaline 1700 Video	n/a	Inc. w/Scanner	

<a href="#">Bell &amp; Howell 2138A Video</a>	Adrenaline 1700 Video	n/a	SC-1012-0000	*
<a href="#">Bell &amp; Howell 3338/3338A Video</a>	Adrenaline 850 Video	n/a	SC-1012-0000	*
<a href="#">Bell &amp; Howell 3338/3338A Video</a>	Adrenaline 1700 Video	n/a	SC-1012-0000	
<a href="#">Bell &amp; Howell 4040S/4040D SCSI</a>	Adrenaline 850 SCSI	n/a	SC-1028-0000	*
<a href="#">Bell &amp; Howell 4040S/4040D SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1028-0000	*
<a href="#">Bell &amp; Howell 4040S/4040D SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1028-0000	*
<a href="#">Bell &amp; Howell 4040S/4040D SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1028-0000	
<a href="#">Bell &amp; Howell 4040S/4040D SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Bell &amp; Howell 500FB SCSI</a>	Adrenaline 650i SCSI	n/a		*
<a href="#">Bell &amp; Howell 500FB SCSI</a>	Adrenaline 650 SCSI	n/a		*
<a href="#">Bell &amp; Howell 500FB SCSI</a>	Adrenaline 450 SCSI	n/a		*
<a href="#">Bell &amp; Howell 500FB SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Bell &amp; Howell 500FB SCSI</a>	n/a	Software VRS 1.20.03	n/a	*
<a href="#">Bell &amp; Howell 6338A Video</a>	Adrenaline 1700 Video	n/a	SC-1022-0000	*
<a href="#">Bell &amp; Howell 730DC FB SCSI</a>	Adrenaline 650i SCSI	n/a		*
<a href="#">Bell &amp; Howell 730DC FB SCSI</a>	Adrenaline 650 SCSI	n/a		*
<a href="#">Bell &amp; Howell 730DC FB SCSI</a>	Adrenaline 450 SCSI	n/a		*
<a href="#">Bell &amp; Howell 8080/8125 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	*
<a href="#">Bell &amp; Howell 8080/8125 SCSI</a>	n/a	AIPE 3.65.38	n/a	
<a href="#">Bell &amp; Howell 8080/8125 Video</a>	Adrenaline 1700 Video	n/a	SC-1023-0000	*

<a href="#">Bell &amp; Howell 8080/8125 VRS Ready Video</a>	Adrenaline 1700 Video	n/a	Inc. w/Scanner	*
<hr/>				
<a href="#">Canon DR-3020 SCSI</a>	Adrenaline 850 SCSI	n/a	SC-1026-0000	*
<a href="#">Canon DR-3020 SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1026-0000	*
<a href="#">Canon DR-3020 SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1026-0000	*
<a href="#">Canon DR-3020 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	
<a href="#">Canon DR-3020 SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<hr/>				
<a href="#">Canon DR-3060 SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1026-0000	
<a href="#">Canon DR-3060 SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1026-0000	
<a href="#">Canon DR-3060 SCSI</a>	n/a	AIPE 3.65.38	n/a	
<hr/>				
<a href="#">Canon DR-3080C SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1026-0000	*
<a href="#">Canon DR-3080C SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1026-0000	*
<a href="#">Canon DR-3080C SCSI</a>	Adrenaline 450 SCSI	n/a	SC-1024-0000	*
<a href="#">Canon DR-3080C SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<hr/>				
<a href="#">Canon DR-4080U SCSI</a>	Adrenaline 850 SCSI	n/a	SC-1026-0000	
<a href="#">Canon DR-4080U SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1026-0000	*
<a href="#">Canon DR-4080U SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1026-0000	*
<a href="#">Canon DR-4080U SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	*
<a href="#">Canon DR-4080U SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Canon DR-4080U SCSI</a>	n/a	Software VRS 1.20.03	n/a	*
<hr/>				
<a href="#">Canon DR-5020 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	*
<a href="#">Canon DR-5020 SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<hr/>				
<a href="#">Canon DR-5060F SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1026-0000	

<a href="#">Canon DR-5060F SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1026-0000	
<a href="#">Canon DR-5080C SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	*
<a href="#">Canon DR-5080C SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Canon DR-5080C SCSI</a>	n/a	Software VRS 1.20.03	n/a	*
<a href="#">Fujitsu fi-4750C SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1026-0000	*
<a href="#">Fujitsu fi-4750C SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1026-0000	*
<a href="#">Fujitsu fi-4750C SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Fujitsu fi-4750L SCSI</a>	Adrenaline 850 SCSI	n/a	SC-1026-0000	*
<a href="#">Fujitsu fi-4750L SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	
<a href="#">Fujitsu M3093DE Video</a>	Adrenaline 850 Video	n/a	SC-1010-0000	*
<a href="#">Fujitsu M3093DE Video</a>	Adrenaline 1700 Video	n/a	SC-1010-0000	
<a href="#">Fujitsu M3093DG SCSI</a>	Adrenaline 850 SCSI	n/a	SC-1028-0000	*
<a href="#">Fujitsu M3093DG SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1028-0000	*
<a href="#">Fujitsu M3093DG SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1028-0000	*
<a href="#">Fujitsu M3093DG SCSI</a>	Adrenaline 450 SCSI	n/a	SC-1016-0000	*
<a href="#">Fujitsu M3093DG SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1028-0000	
<a href="#">Fujitsu M3093DG SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Fujitsu M3093EX Video</a>	Adrenaline 850 Video	n/a	SC-1010-0000	*
<a href="#">Fujitsu M3093EX Video</a>	Adrenaline 1700 Video	n/a	SC-1010-0000	
<a href="#">Fujitsu M3093GX SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Fujitsu M3093GX SCSI</a>	n/a	Software VRS 1.20.03	n/a	*

<a href="#">Fujitsu M3096E/E+ Video</a>	Adrenaline 1700 Video	n/a	SC-1010-0000	
<a href="#">Fujitsu M3096EX Video</a>	Adrenaline 850 Video	n/a	SC-1010-0000	*
<a href="#">Fujitsu M3096EX Video</a>	Adrenaline 1700 Video	n/a	SC-1010-0000	
<a href="#">Fujitsu M3096GX SCSI</a>	Adrenaline 850 SCSI	n/a	SC-1028-0000	*
<a href="#">Fujitsu M3096GX SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1028-0000	
<a href="#">Fujitsu M3096GX SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Fujitsu M3097 VRS Video</a>	Adrenaline 850 Video	n/a	Inc. w/Scanner	*
<a href="#">Fujitsu M3097 VRS Video</a>	Adrenaline 1700 Video	n/a	Inc. w/Scanner	
<a href="#">Fujitsu M3097DE Video</a>	Adrenaline 850 Video	n/a	SC-1010-0000	*
<a href="#">Fujitsu M3097DE Video</a>	Adrenaline 1700 Video	n/a	SC-1010-0000	
<a href="#">Fujitsu M3097DG SCSI</a>	Adrenaline 850 SCSI	n/a	SC-1028-0000	*
<a href="#">Fujitsu M3097DG SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1028-0000	
<a href="#">Fujitsu M3097DG SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Fujitsu M3099EH Video</a>	Adrenaline 1700 Video	n/a	SC-1010-0000	*
<a href="#">Fujitsu M3099EX Video</a>	Adrenaline 1700 Video	n/a	SC-1010-0000	*
<a href="#">Fujitsu M3099GH SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1028-0000	*
<a href="#">Fujitsu M3099GH SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Fujitsu M3099GX SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1028-0000	*
<a href="#">Fujitsu M3099GX SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Fujitsu M4097D SCSI</a>	Adrenaline 850 SCSI	n/a	SC-1026-0000	*

<a href="#">Fujitsu M4097D SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1026-0000	*
<a href="#">Fujitsu M4097D SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1026-0000	*
<a href="#">Fujitsu M4097D SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	
<a href="#">Fujitsu M4097D SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<hr/>				
<a href="#">Fujitsu M4097D Video</a>	Adrenaline 850 Video	n/a	SC-1010-0000	*
<a href="#">Fujitsu M4097D Video</a>	Adrenaline 1700 Video	n/a	SC-1010-0000	
<hr/>				
<a href="#">Fujitsu M4097D VRS SCSI</a>	Adrenaline 850 SCSI	n/a	SC-1027-0000	*
<a href="#">Fujitsu M4097D VRS SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1027-0000	*
<hr/>				
<a href="#">Fujitsu M4099D SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	*
<a href="#">Fujitsu M4099D SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<hr/>				
<a href="#">Fujitsu M4099D VRS SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1027-0000	*
<hr/>				
<a href="#">Fujitsu ScanPartner 15C SCSI</a>	Adrenaline 650i SCSI	n/a		*
<a href="#">Fujitsu ScanPartner 15C SCSI</a>	Adrenaline 650 SCSI	n/a		*
<a href="#">Fujitsu ScanPartner 15C SCSI</a>	Adrenaline 450 SCSI	n/a		*
<a href="#">Fujitsu ScanPartner 15C SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<hr/>				
<a href="#">Fujitsu ScanPartner 3091DC SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1026-0000	*
<a href="#">Fujitsu ScanPartner 3091DC SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1026-0000	*
<a href="#">Fujitsu ScanPartner 3091DC SCSI</a>	Adrenaline 450 SCSI	n/a	SC-1024-0000	*
<a href="#">Fujitsu ScanPartner 3091DC SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Fujitsu ScanPartner 3091DC SCSI</a>	n/a	Software VRS 1.20.03	n/a	*
<hr/>				
<a href="#">Fujitsu ScanPartner 3092DC SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1026-0000	*

<a href="#"><u>Fujitsu ScanPartner 3092DC SCSI</u></a>	Adrenaline 650 SCSI	n/a	SC-1026-0000	*
<a href="#"><u>Fujitsu ScanPartner 3092DC SCSI</u></a>	Adrenaline 450 SCSI	n/a	SC-1024-0000	*
<a href="#"><u>Fujitsu ScanPartner 3092DC SCSI</u></a>	n/a	AIPE 3.65.38	n/a	*
<a href="#"><u>Fujitsu ScanPartner 3092DC SCSI</u></a>	n/a	Software VRS 1.20.03	n/a	*
<hr/>				
<a href="#"><u>Fujitsu ScanPartner 600C SCSI</u></a>	Adrenaline 650i SCSI	n/a		*
<a href="#"><u>Fujitsu ScanPartner 600C SCSI</u></a>	Adrenaline 650 SCSI	n/a		*
<a href="#"><u>Fujitsu ScanPartner 600C SCSI</u></a>	Adrenaline 450 SCSI	n/a		*
<a href="#"><u>Fujitsu ScanPartner 600C SCSI</u></a>	n/a	AIPE 3.65.38	n/a	*
<hr/>				
<a href="#"><u>Fujitsu ScanPartner 620C SCSI</u></a>	Adrenaline 650i SCSI	n/a		*
<a href="#"><u>Fujitsu ScanPartner 620C SCSI</u></a>	Adrenaline 650 SCSI	n/a		*
<a href="#"><u>Fujitsu ScanPartner 620C SCSI</u></a>	Adrenaline 450 SCSI	n/a		*
<a href="#"><u>Fujitsu ScanPartner 620C SCSI</u></a>	n/a	AIPE 3.65.38	n/a	*
<hr/>				
<a href="#"><u>Fujitsu ScanPartner 93 SCSI</u></a>	Adrenaline 850 SCSI	n/a	SC-1026-0000	*
<a href="#"><u>Fujitsu ScanPartner 93 SCSI</u></a>	Adrenaline 650i SCSI	n/a	SC-1026-0000	*
<a href="#"><u>Fujitsu ScanPartner 93 SCSI</u></a>	Adrenaline 650 SCSI	n/a	SC-1026-0000	*
<a href="#"><u>Fujitsu ScanPartner 93 SCSI</u></a>	Adrenaline 450 SCSI	n/a	SC-1024-0000	*
<a href="#"><u>Fujitsu ScanPartner 93 SCSI</u></a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	*
<a href="#"><u>Fujitsu ScanPartner 93 SCSI</u></a>	n/a	AIPE 3.65.38	n/a	*
<hr/>				
<a href="#"><u>Hewlett-Packard 6250 SCSI</u></a>	Adrenaline 650i SCSI	n/a		*
<a href="#"><u>Hewlett-Packard 6250 SCSI</u></a>	Adrenaline 650 SCSI	n/a		*
<a href="#"><u>Hewlett-Packard 6250 SCSI</u></a>	Adrenaline 450 SCSI	n/a		*
<a href="#"><u>Hewlett-Packard 6250 SCSI</u></a>	n/a	AIPE 3.65.38	n/a	*
<a href="#"><u>Hewlett-Packard 6250 SCSI</u></a>	n/a	Software VRS 1.20.03	n/a	*

<a href="#">Hewlett-Packard 6300Cxi SCSI</a>	Adrenaline 650i SCSI	n/a		*
<a href="#">Hewlett-Packard 6300Cxi SCSI</a>	Adrenaline 650 SCSI	n/a		*
<a href="#">Hewlett-Packard 6300Cxi SCSI</a>	Adrenaline 450 SCSI	n/a		*
<a href="#">Hewlett-Packard 6300Cxi SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Hewlett-Packard 6300Cxi SCSI</a>	n/a	Software VRS 1.20.03	n/a	*
<a href="#">Hewlett-Packard 6350Cxi SCSI</a>	Adrenaline 650i SCSI	n/a		*
<a href="#">Hewlett-Packard 6350Cxi SCSI</a>	Adrenaline 650 SCSI	n/a		*
<a href="#">Hewlett-Packard 6350Cxi SCSI</a>	Adrenaline 450 SCSI	n/a		*
<a href="#">Hewlett-Packard 6350Cxi SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Hewlett-Packard 6350Cxi SCSI</a>	n/a	Software VRS 1.20.03	n/a	*
<a href="#">InoTec SCAMAX 2600 SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1026-0000	*
<a href="#">InoTec SCAMAX 2600 SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1026-0000	*
<a href="#">InoTec SCAMAX 2600 SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Kodak ds1500 SCSI</a>	Adrenaline 850 SCSI	n/a	SC-1026-0000	*
<a href="#">Kodak ds1500 SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1026-0000	*
<a href="#">Kodak ds1500 SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1026-0000	*
<a href="#">Kodak ds1500 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	
<a href="#">Kodak ds1500 SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Kodak ds1500 SCSI</a>	n/a	Software VRS 1.20.03	n/a	*
<a href="#">Kodak ds2500 SCSI</a>	Adrenaline 850 SCSI	n/a	SC-1026-0000	*
<a href="#">Kodak ds2500 SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1026-0000	*
<a href="#">Kodak ds2500 SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1026-0000	*

<a href="#">Kodak ds2500 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	
<a href="#">Kodak ds2500 SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Kodak ds3500 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	*
<a href="#">Kodak ds3500 SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Kodak ds3510 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	*
<a href="#">Kodak ds3510 SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Kodak ds3520 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	*
<a href="#">Kodak ds3520 SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Kodak ds3590c SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	*
<a href="#">Kodak ds4500 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	*
<a href="#">Kodak ds4500 SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Kodak ds5500 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1028-0000	*
<a href="#">Kodak ds7500 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1028-0000	*
<a href="#">Kodak ds7520 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1028-0000	*
<a href="#">Kodak ds9500 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1028-0000	*
<a href="#">Kodak ds9520 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1028-0000	*
<a href="#">Kodak i50 SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1028-0000	*
<a href="#">Kodak i50 SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1028-0000	*

<a href="#">Kodak i50 SCSI</a>	Adrenaline 450 SCSI	n/a	SC-1016-0000	*
<a href="#">Kodak i50 SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Kodak i60 SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1028-0000	*
<a href="#">Kodak i60 SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1028-0000	*
<a href="#">Kodak i60 SCSI</a>	Adrenaline 450 SCSI	n/a	SC-1016-0000	*
<a href="#">Kodak i810 SCSI</a>	Adrenaline 650i SCSI	n/a		
<a href="#">Kodak i810 SCSI</a>	Adrenaline 650 SCSI	n/a		
<a href="#">Kodak i820 SCSI</a>	Adrenaline 650i SCSI	n/a		
<a href="#">Kodak i820 SCSI</a>	Adrenaline 650 SCSI	n/a		
<a href="#">Kodak i830 SCSI</a>	Adrenaline 650i SCSI	n/a		
<a href="#">Kodak i830 SCSI</a>	Adrenaline 650 SCSI	n/a		
<a href="#">Kodak i840 SCSI</a>	Adrenaline 650i SCSI	n/a		
<a href="#">Kodak i840 SCSI</a>	Adrenaline 650 SCSI	n/a		
<a href="#">Kodak IL500 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1028-0000	*
<a href="#">Kodak IL900/923 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1028-0000	*
<a href="#">Kodak IL990/ds990 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1028-0000	*
<a href="#">Panasonic KV-S2065 SCSI</a>	Adrenaline 850 SCSI	n/a	SC-1026-0000	*
<a href="#">Panasonic KV-S2065 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	*
<a href="#">Panasonic KV-S6040 SCSI</a>	Adrenaline 850 SCSI	n/a	SC-1026-0000	*
<a href="#">Panasonic KV-S6040 SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1026-0000	*

<a href="#">Panasonic KV-S6040 SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1026-0000	*
<a href="#">Panasonic KV-S6040 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	
<a href="#">Panasonic KV-S6040 SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Panasonic KV-S6040 SCSI</a>	n/a	Software VRS 1.20.03	n/a	*
<hr/>				
<a href="#">Panasonic KV-S6045 SCSI</a>	Adrenaline 850 SCSI	n/a	SC-1026-0000	*
<a href="#">Panasonic KV-S6045 SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1026-0000	*
<a href="#">Panasonic KV-S6045 SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1026-0000	*
<a href="#">Panasonic KV-S6045 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	
<a href="#">Panasonic KV-S6045 SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<a href="#">Panasonic KV-S6045 SCSI</a>	n/a	Software VRS 1.20.03	n/a	*
<hr/>				
<a href="#">Panasonic KV-S6055 SCSI</a>	Adrenaline 850 SCSI	n/a	SC-1026-0000	*
<a href="#">Panasonic KV-S6055 SCSI</a>	Adrenaline 650i SCSI	n/a	SC-1026-0000	*
<a href="#">Panasonic KV-S6055 SCSI</a>	Adrenaline 650 SCSI	n/a	SC-1026-0000	*
<a href="#">Panasonic KV-S6055 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	*
<a href="#">Panasonic KV-S6055 SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<hr/>				
<a href="#">Panasonic KV-SS2055 SCSI</a>	Adrenaline 850 SCSI	n/a	SC-1026-0000	*
<a href="#">Panasonic KV-SS2055 SCSI</a>	Adrenaline 850 SCSI	n/a	SC-1026-0000	*
<a href="#">Panasonic KV-SS2055 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	
<a href="#">Panasonic KV-SS2055 SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	
<hr/>				
<a href="#">Panasonic KV-SS855/855D SCSI</a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	*
<a href="#">Panasonic KV-SS855/855D SCSI</a>	n/a	AIPE 3.65.38	n/a	*
<hr/>				
<a href="#">Panasonic SS-25 SCSI</a>	Adrenaline 650i SCSI	n/a		*
<a href="#">Panasonic SS-25 SCSI</a>	Adrenaline 650 SCSI	n/a		*

[Panasonic SS-25 SCSI](#) Adrenaline 450 SCSI n/a \*

[Panasonic SS-25 SCSI](#) n/a AIPE 3.65.38 n/a \*

---

[Panasonic SS-55 SCSI](#) Adrenaline 650i SCSI n/a \*

[Panasonic SS-55 SCSI](#) Adrenaline 650 SCSI n/a \*

[Panasonic SS-55 SCSI](#) Adrenaline 450 SCSI n/a \*

[Panasonic SS-55 SCSI](#) n/a AIPE 3.65.38 n/a \*

---

[Ricoh IS01 SCSI](#) Adrenaline 650i SCSI n/a \*

[Ricoh IS01 SCSI](#) Adrenaline 650 SCSI n/a \*

[Ricoh IS01 SCSI](#) Adrenaline 450 SCSI n/a \*

[Ricoh IS01 SCSI](#) n/a AIPE 3.65.38 n/a \*

[Ricoh IS01 SCSI](#) n/a Software VRS 1.20.03 n/a \*

---

[Ricoh IS330 SCSI](#) Adrenaline 650i SCSI n/a \*

[Ricoh IS330 SCSI](#) Adrenaline 650 SCSI n/a \*

[Ricoh IS330 SCSI](#) Adrenaline 450 SCSI n/a \*

[Ricoh IS330 SCSI](#) n/a AIPE 3.65.38 n/a \*

---

[Ricoh IS420 SCSI](#) Adrenaline 850 SCSI n/a SC-1026-0000 \*

[Ricoh IS420 SCSI](#) Adrenaline 1700 SCSI n/a SC-1026-0000

[Ricoh IS420 SCSI](#) n/a AIPE 3.65.38 n/a \*

---

[Ricoh IS420 Video](#) Adrenaline 850 Video n/a SC-1010-0000 \*

[Ricoh IS420 Video](#) Adrenaline 1700 Video n/a SC-1010-0000

---

[Ricoh IS450 DE SCSI](#) Adrenaline 850 SCSI n/a SC-1026-0000 \*

[Ricoh IS450 DE SCSI](#) Adrenaline 1700 SCSI n/a SC-1026-0000

<a href="#"><u>Ricoh IS450 DE SCSI</u></a>	n/a	AIPE 3.65.38	n/a	*
--------------------------------------------	-----	--------------	-----	---

---

<a href="#"><u>Ricoh IS450 SE SCSI</u></a>	Adrenaline 850 SCSI	n/a	SC-1026-0000	*
--------------------------------------------	---------------------	-----	--------------	---

<a href="#"><u>Ricoh IS450 SE SCSI</u></a>	Adrenaline 1700 SCSI	n/a	SC-1026-0000	
--------------------------------------------	----------------------	-----	--------------	--

<a href="#"><u>Ricoh IS450 SE SCSI</u></a>	n/a	AIPE 3.65.38	n/a	*
--------------------------------------------	-----	--------------	-----	---

---

<a href="#"><u>Ricoh IS450DE VRS Video</u></a>	Adrenaline 850 Video	n/a	Inc. w/Scanner	*
------------------------------------------------	----------------------	-----	----------------	---

<a href="#"><u>Ricoh IS450DE VRS Video</u></a>	Adrenaline 1700 Video	n/a	Inc. w/Scanner	
------------------------------------------------	-----------------------	-----	----------------	--

\* = A Recommended Configuration

---



Scanner	Software Engine	
<a href="#">Agfa ADMIS S 31 SCSI</a>	AIPE 3.65.38	*
<a href="#">Bell &amp; Howell 1000FB/5000F SCSI</a>	AIPE 3.65.38	*
<a href="#">Bell &amp; Howell 2000D FB SCSI</a>	AIPE 3.65.38	*
<a href="#">Bell &amp; Howell 4040S/4040D SCSI</a>	AIPE 3.65.38	*
<a href="#">Bell &amp; Howell 500FB SCSI</a>	AIPE 3.65.38	*
<a href="#">Bell &amp; Howell 500FB SCSI</a>	Software VRS 1.20.03	*
<a href="#">Bell &amp; Howell 8080/8125 SCSI</a>	AIPE 3.65.38	
<a href="#">Canon DR-3020 SCSI</a>	AIPE 3.65.38	*
<a href="#">Canon DR-3060 SCSI</a>	AIPE 3.65.38	
<a href="#">Canon DR-3080C SCSI</a>	AIPE 3.65.38	*
<a href="#">Canon DR-4080U SCSI</a>	AIPE 3.65.38	*
<a href="#">Canon DR-4080U SCSI</a>	Software VRS 1.20.03	*
<a href="#">Canon DR-5020 SCSI</a>	AIPE 3.65.38	*
<a href="#">Canon DR-5080C SCSI</a>	AIPE 3.65.38	*
<a href="#">Canon DR-5080C SCSI</a>	Software VRS 1.20.03	*
<a href="#">Fujitsu fi-4750C SCSI</a>	AIPE 3.65.38	*
<a href="#">Fujitsu M3093DG SCSI</a>	AIPE 3.65.38	*
<a href="#">Fujitsu M3093GX SCSI</a>	AIPE 3.65.38	*
<a href="#">Fujitsu M3093GX SCSI</a>	Software VRS 1.20.03	*
<a href="#">Fujitsu M3096GX SCSI</a>	AIPE 3.65.38	*
<a href="#">Fujitsu M3097DG SCSI</a>	AIPE 3.65.38	*
<a href="#">Fujitsu M3099GH SCSI</a>	AIPE 3.65.38	*

<a href="#"><u>Fujitsu M3099GX SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Fujitsu M4097D SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Fujitsu M4099D SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Fujitsu ScanPartner 15C SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Fujitsu ScanPartner 3091DC SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Fujitsu ScanPartner 3091DC SCSI</u></a>	Software VRS 1.20.03	*
<a href="#"><u>Fujitsu ScanPartner 3092DC SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Fujitsu ScanPartner 3092DC SCSI</u></a>	Software VRS 1.20.03	*
<a href="#"><u>Fujitsu ScanPartner 600C SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Fujitsu ScanPartner 620C SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Fujitsu ScanPartner 93 SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Hewlett-Packard 6250 SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Hewlett-Packard 6250 SCSI</u></a>	Software VRS 1.20.03	*
<a href="#"><u>Hewlett-Packard 6300Cxi SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Hewlett-Packard 6300Cxi SCSI</u></a>	Software VRS 1.20.03	*
<a href="#"><u>Hewlett-Packard 6350Cxi SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Hewlett-Packard 6350Cxi SCSI</u></a>	Software VRS 1.20.03	*
<a href="#"><u>InoTec SCAMAX 2600 SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Kodak ds1500 SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Kodak ds1500 SCSI</u></a>	Software VRS 1.20.03	*
<a href="#"><u>Kodak ds2500 SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Kodak ds3500 SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Kodak ds3510 SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Kodak ds3520 SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Kodak ds4500 SCSI</u></a>	AIPE 3.65.38	*

<a href="#"><u>Kodak i50 SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Panasonic KV-S6040 SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Panasonic KV-S6040 SCSI</u></a>	Software VRS 1.20.03	*
<a href="#"><u>Panasonic KV-S6045 SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Panasonic KV-S6045 SCSI</u></a>	Software VRS 1.20.03	*
<a href="#"><u>Panasonic KV-S6055 SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Panasonic KV-SS855/855D SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Panasonic SS-25 SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Panasonic SS-55 SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Ricoh IS01 SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Ricoh IS01 SCSI</u></a>	Software VRS 1.20.03	*
<a href="#"><u>Ricoh IS330 SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Ricoh IS420 SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Ricoh IS450 DE SCSI</u></a>	AIPE 3.65.38	*
<a href="#"><u>Ricoh IS450 SE SCSI</u></a>	AIPE 3.65.38	*

---